

BENTON COUNTY

SITE ID:	L & L Exxon		Cleanup Site ID: 7128		FS ID: 78835792
	Alternate Name(s): L & L Exxon, LEOS LINEUP & TIRES AUTO EXPRESS				
LOCATION:	WRIA: 40		Lat/Long: 46.275 -119.281		View Vicinity Map
Address:	1315 LEE BLVD		Township	Range	Section
	RICHLAND	99352	9N	28E	11
					Legislative District: 8
					Congressional District: 4
STATUS:	Cleanup Started		Rank: 2		View Site Web Page
	Responsible Unit: Central	Site Manager: Klasner, Laura		Statute: MTCA	
	Is Brownfield?	Has Environmental Covenant?		Is PSI Site?	
	NFA Received?	NFA Date:		NFA Reason:	

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
4766	L & L EXXON	Upland	Ecology-supervised or conducted	Cleanup Started		C502779

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received			2/25/1999			Bassett, Dick
CleanupSite		Site Discovery/Release Report Received			8/28/1989			George, Dave
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	5/14/1999	5/24/1999		Ecology	Bassett, Dick
CleanupSite		Early Notice Letter(s)			11/28/2007			Plath, Brianne
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	5/6/2010	8/17/2010		Local Government	Local Government-CE
CleanupSite		Hazardous Sites Listing/NPL			8/18/2010			Smith, Frosti
CleanupSite MilestoneType		Ecology Interim Action Plan	Completed	9/1/2014	11/14/2014	Governmental Action	Ecology w/ Contractor	Lind, Jennifer
LUST	18	LUST - Notification		8/28/1989	8/28/1989			
LUST	6068	LUST - Notification		2/25/1999	2/25/1999			
LUST	6068	LUST - Site Assessment Report			3/19/1999			
LUST	6068	LUST - Report Received		3/25/2014	3/27/2014			
LUST	6068	LUST - Report Received		5/24/2013	6/7/2013			
LUST	6068	LUST - Report Received		3/6/2013	3/6/2013			

LUST	6068	LUST - Report Received		4/5/2013	4/10/2013				
LUST	6068	LUST - Report Received		2/21/2014	2/24/2014				
LUST	6068	LUST - Report Received		2/26/2015	3/2/2015				
LUST	18	LUST - Report Received		8/28/1989	8/28/1989				
LUST	6068	LUST - Report Received		4/11/2013	4/17/2013				

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Petroleum-Gasoline	C		C			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014